



T.I.P. Troubleshooting Information on Power Gear

FLOAT SWITCH IDENTIFICATION

MODEL	PRODUCTION	FLOAT SWITCH REQUIRED
American Eagle, Dream, Pace Arrow Pusher	July 1993 - Current	500119
Bounder, Southwind, Pace Arrow	July 1993 - Dec. 1993	500118
	Jan 1994 production - current	500199
Gasket Repair Kit	For 500119 and 500199 Switches	500188*

Service Notes:

1. Replace entire switch if switch continuity is bad or if oil leaks from between the switch wires.
2. *If switch is good but oil leaks from around tank grommet, just replace grommet - 500188.



T.I.P. Troubleshooting Information on Power Gear