

Other Helpful Information:

Carlisle Brite-Ply EPDM roofing membrane is specially formulated for exposure to the sun and natural elements. However, it can be cut or punctured by sharp objects. Use caution when placing any articles or walking on the roof. If damage does occur, the Brite-Ply membrane can easily be repaired using Dicor's #401-PR or #402-PR roof repair kits. Contact your local dealer or Dicor Corporation.

Cleaning lap sealant used around roof mounted accessories and railings: If soap and water do not clean the seal to your satisfaction, use a cloth dampened with mineral spirits to wipe away dirt build-up on the seal.

Repairing lap sealant or adding sealant: If, after a period of time, the lap sealant needs touched up or additional seal is needed, use a cloth dampened with mineral spirits to eliminate all foreign materials from the surface of the seal. Let set for at least 15 minutes and apply Dicor lap sealant (#501LS, 502LS or 551LS) directly over the existing seal – allowing the new sealant to touch the EPDM and/or accessory surface.

If addition UV protection is desired, apply Dicor's RP-RG320S Rubber Roof Guard Protectant immediately after cleaning.