

2-Stage Furnace Diagnostics

FLASHES	DIAGNOSTIC INFORMATION	LOCKOUT
1	Low Input voltage	SOFT
2	Ignition Failure	SOFT
3	Open High Limit	SOFT
4	Stuck Sail Switch	HARD
5	Module Fault	HARD

lockout is a condition that is timed and will make the furnace unable to start until the problem is corrected. A SOFT lockout requires a power cycle or turning the power switch off then back on. A HARD lockout requires a power cycle or turning the power switch off then back on, and also requires a manual reset via a hard switch or mostat or turning the power switch off then back on.