



Service Bulletin

Correct DC Wiring on Models 442 and 443

The original label on the terminal block of the refrigerator may be incorrect. Model numbers 442 and 443 with serial numbers lower than 636275 have an incorrect terminal block label.

If your refrigerator model 442 or 443 has the original incorrect label, part number 620051A, use these instructions to install the replacement label part number 620448A on the terminal block of the refrigerator and insure that the DC wiring is correctly attached.

Install the Replacement Label

1. Disconnect the DC wiring attached at the terminal block.
2. Install the replacement label on the terminal block of the refrigerator as follows:
 - Remove the backing from the replacement label exposing the adhesive surface.
 - Align the replacement label over the original label on the terminal block.
 - Make sure the replacement label covers the original label.

Make Sure the DC Wiring is Correctly Reconnected

- Look at the replacement label.
- See that the (+) positive terminal for the DC wiring is on the left.
- Make sure that the (+) positive DC red wire is attached to the (+) positive terminal of the terminal block.
- Make sure that the (-) negative DC black wire is attached to the (-) negative terminal of the terminal block.



WARNING: If the (+) positive DC wiring is not attached to the left DC terminal (as shown on the replacement labels), the DC fuse of the refrigerator will not protect the refrigerator components.

