


Bulletin Number: RV-001
Effective: October 1, 1990

NEW FOUR-BOLT FLOOR FLANGES


Affected Models: *All Traveler® toilets.*

New Product Information: *The Traveler toilet requires a four-bolt style floor flange. In the past, four-bolt flanges were only available in a limited number of configurations (such as 3" MPT but not 3" socket). Not all four-bolt flanges have been listed by both IAPMO (UPC), the U.S. plumbing approval authority, and Canadian Standards Association (CSA), the Canadian approval authority. SeaLand has developed a new heavy-duty four-bolt flange available in both 3" MPT and 3" socket configurations. Both configurations have been accepted by UPC and CSA.*


An important feature of SeaLand's new flange is an indexing system to make proper alignment for all gravity discharge toilets a simple operation. The flange is marked with three arrows. Each arrow represents the correct bolt alignment for a different toilet mounting system. Please refer to the following illustrations.



Position 1 is for use with SeaLand toilets.



Position 2 is for two bolt toilets with a 3 o'clock & 9 o'clock alignment. Such as Thetford AquaMagic IV, Sanitation Equipment Perma Flush and Valterra LeToilete.



Position 3 is for two bolt units such as AquaMagic Galaxy or Starlite.

Ordering Information: *SeaLand flanges can be ordered under the following Part Numbers:*

345892 - 4 X 3 Closet Flange with 3" socket

345889 - 4 X 3 Closet Flange with 3" MPT